

Version 13.0.1

Standard allPIXAneo NXGE

Component Versions

Variant	Version
Bitstream	30.2.0
Application/XML	21.1.0
Bootfile	25.1.2
Feature Reference	21.1.0
Gamma	KaxGamma03_10

Notes

Changes and new Features

Bug Fixes

- Disable throughput (DVAL) relaxation to avoid acquisition issues.

Incompatibilities

Errata

- Using LED-Flash and MasterSlave mode together will not work for the slave camera.
 - Independently the features are working.
- When using **MasterSlaveMode** and **FrameActive** the incoming frame active signal must not exceed the configured height in the **Height** feature.
 - Otherwise issues on the slave camera will occur.

Docs